



EOL Notification
Document #: 1N5820
Issue Date: 2022/04/21
EOL#: 20220421001

Title of Change:		1N5820 EOL	
Proposed first ship date		NA	
Contact information:		Please contact Rectron Sales Office or visit www.rectron.com for nearest contact information.	
Samples:		Please contact Rectron Sales Office or visit www.rectron.com for nearest contact information. Samples delivery timing will be subject to request date, sample quantity and special customer packing/label requirements.	
Additional Reliability Data:		Please contact Rectron Sales Office or visit www.rectron.com for nearest contact information.	
Type of notification:		This is a EOL (End Of Life) Notification sent to customers. EOL are issued 90 days prior to implementation of the change. Rectron will consider this change accepted, unless an inquiry is made in writing within 30 days of delivery of this notice. To do so, please visit www.rectron.com for nearest contact information	
Change Part Identification:		NA	
Change Category:		<input checked="" type="checkbox"/> Material <input type="checkbox"/> Machine/Tooling <input type="checkbox"/> Method <input type="checkbox"/> Manufacture site <input type="checkbox"/> Man	
Change Sub-Category(s):		<input type="checkbox"/> Manufacturing Site Transfer <input type="checkbox"/> Material Change <input type="checkbox"/> Datasheet/Product Doc change <input type="checkbox"/> Manufacturing Process Change <input type="checkbox"/> Product specific change <input type="checkbox"/> Shipping/Packaging/Marking <input type="checkbox"/> Manufacturing Site Additi <input checked="" type="checkbox"/> Other :EOL	
Last order date for previous version		2022/4/21	
Description and Purpose:		About 1N5820 EOL	
Point:	Change	Before	After
Electrical Characteristic Summary:		NA	
List of Affected Parts:		Note: Only the standard (off the shelf) part numbers are listed in the parts list. Any custom parts affected by this EOL are shown in the customer specific EOL addendum in the PCN email notification, or on the EOL Customized Portal.	
Part Number	Suggest New Part Number	Addition	Mark
1N5820	1N5822	nearest replacement	exceptions